

ERA25LA096

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Frontal View Showing Airplane Where Came to Rest on Runway (Courtesy of FAA)



Photograph 2 - Left Side View Showing Airplane Where Came to Rest on Runway (Courtesy of FAA)



Photograph 3 - Rear View Showing Airplane Where Came to Rest on Runway (Courtesy of FAA)



Photograph 4 - Right Side View Showing Airplane Where Came to Rest on Runway (Courtesy of FAA)



Photograph 5 - View of Right Main Landing Gear in Wheel Well (Courtesy of FAA)



Photograph 6 - View of the Cockpit (Courtesy of FAA)



Photograph 7 - View Showing Separated Upper and Lower Torque Links of Right Main Landing Gear (Courtesy of FAA)



**Photograph 8 - Abrasion Damage to External Longerons on the Bottom of the Fuselage.
(Courtesy of FAA)**