

ERA25LA100

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Main Wreckage Zoom View (Courtesy of FAA)



Photograph 3 - Lower Right Wing Damage (Courtesy of FAA)



Photograph 4 - Upper Right Wing Damage (Courtesy of FAA)