

ERA25LA101

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to lower fuselage Structure (Courtesy of FAA)



Photograph 2 - Deformation noted to copilot's floorboard structure (Courtesy of FAA)