

ERA25LA114


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damaged left wing. (Courtesy of FAA)



Photograph 2 - View of damaged left aileron. (Courtesy of FAA)



Photograph 3 - View of top of left wing damage. (Courtesy of FAA)