

ERA25LA122

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of FAA)



Photograph 2 - Vertical stabilizer accident damage (Courtesy of FAA)



Photograph 3 - Right wing accident damage (Courtesy of FAA)



Photograph 4 - Engine postaccident (Courtesy of FAA)