

ERA25LA123

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Accident airplane inverted (Courtesy of Owner/Pilot)



Photograph 2 - Oil filter and adapter (Courtesy of FAA)



Photograph 3 - Oil temperature probe (Courtesy of Owner/Pilot)



Photograph 4 - Oil temperature probe (Courtesy of Owner/Pilot)



Photograph 5 - Oil temperature probe (Courtesy of Owner/Pilot)