

ERA25LA124

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Sea Tow)



Photograph 2 - Main Wreckage Recovered (Courtesy of WaterFront Operations Manager)