

ERA25LA125

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left gear collapsed, folded under fuselage (Courtesy of Owner)



Photograph 2 - Main wreckage, right wing view (Courtesy of Owner)



Photograph 3 - Front of aircraft and firewall damage (Courtesy of Owner)



Photograph 4 - Main wreckage, left wing view, gear collapsed (Courtesy of Owner)



Photograph 5 - Left main landing gear tube (Courtesy of FAA)



Photograph 6 - Left landing gear tube (Courtesy of FAA)