

ERA25LA135

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of Recovery Company)



Photograph 2 - Right side fuselage accident damage (Courtesy of maintenance)



Photograph 3 - Right main landing gear pylon accident damage (Courtesy of maintenance)



Photograph 4 - Left wing accident damage (Courtesy of FAA)