

ERA25LA138

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front View of Main Wreckage (Courtesy of FAA)



Photograph 2 - Left Side View (Courtesy of FAA)



Photograph 3 - Rear View (Courtesy of FAA)



Photograph 4 - Right Rear Quarter View (Courtesy of FAA)



Photograph 5 - Right Side View (Courtesy of FAA)



Photograph 6 - Right Front Quarter View (Courtesy of FAA)



Photograph 7 - Propeller Strike (Courtesy of FAA)



Photograph 8 - Left Wing Tip (Courtesy of FAA)



Photograph 9 - Aft Right Wing Fuselage Junction (Courtesy of FAA)



Photograph 10 - Close Up of Wing Fuselage Juncture (Courtesy of FAA)



Photograph 11 - Right Aileron (Courtesy of FAA)



Photograph 12 - Right Wing Outboard Leading Edge (Courtesy of FAA)



Photograph 13 - Right Wing Mid-Span Leading Edge (Courtesy of FAA)



Photograph 14 - Underside of Inboard Right Wing (Courtesy of FAA)



Photograph 15 - Close Up of Underside of Inboard Right Wing (Courtesy of FAA)



Photograph 16 - Side View of Underside of Inboard Right Wing (Courtesy of FAA)



Photograph 17 - Right Rear Corner of Truck (Courtesy of FAA)



Photograph 18 - Close Up of Right Rear Corner of Truck (Courtesy of FAA)