

ERA25LA141

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of right side of airplane showing damaged right wing.
(Courtesy of FAA)**



**Photograph 2 - Close up view of damaged right wing.
(Courtesy of FAA)**