

ERA25LA153

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of airplane on site. (Courtesy of FAA)



Photograph 2 - View of wing damage. (Courtesy of FAA)



Photograph 3 - View of landing gear ground tracks leading up to airplane. (Courtesy of FAA)