

ERA25LA157

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left-Wing Leading-Edge Damage (Courtesy of FAA)



Photograph 2 - Hole in engine case (Courtesy of FAA)



Photograph 3 - Oil filter adapter, Note: gasket protruding and leaking oil (Courtesy of FAA)



Photograph 4 - Bottom of fuselage covered in oil (Courtesy of FAA)