

ERA25LA160

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to main rotor blades (Courtesy of FAA)



Photograph 2 - Deformation noted to tail boom (Courtesy of FAA)