

ERA25LA180

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Upper fuselage accident damage (Courtesy of Pilot)



Photograph 2 - Lower fuselage accident damage (Courtesy of Pilot)



Photograph 3 - Vertical stabilizer and rudder accident damage (Courtesy of Pilot)



Photograph 4 - Engine mount and firewall structure accident damage (Courtesy of Pilot)