

ERA25LA181

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Glider at accident site (Source: Pilot)



Photograph 2 - Glider at accident site (Source: Pilot)



Photograph 3 - Damage to right wing (Source: Pilot)



Photograph 4 - Damage to left wing (Source: Pilot)



Photograph 5 - Damage to left wing (Source: Pilot)