

ERA25LA194

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right profile view of airplane at accident site. Note damage to right wing and engine compartment. (Courtesy of FAA)



Photograph 2 - Aft view of airplane looking forward. (Courtesy of FAA)



Photograph 3 - View of airframe and engine compartment damage. (Courtesy of FAA)