

ERA25LA198

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - main wreckage (Courtesy of FAA)**



**Photograph 2 - Main wreckage (Courtesy of FAA)**



**Photograph 3 - Engine, note: Air discharge duct missing. (Courtesy of FAA)**