

ERA25LA200

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Left Side Empennage Damage (Courtesy of FAA)



Photograph 3 - Left Side Empennage Damage (Courtesy of FAA)



Photograph 4 - Fuel Selector (Courtesy of FAA)