

ERA25LA203

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Overall view of airframe and engine wreckage. (NTSB)



Photograph 2 - Left wing damage. (NTSB)



Photograph 3 - View of engine and airframe wreckage. (NTSB)



Photograph 4 - Closeup view of propeller damage. (NTSB)



Photograph 5 - Entire profile view of engine with cowling removed. (NTSB)



Photograph 6 - Topside of engine. (NTSB)



Photograph 7 - Engine Control Unit. (NTSB)