

ERA25LA213

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Left aft quarter view of airplane at rest. Note collapsed left landing gear.
(Courtesy of FAA)**



Photograph 2 - Closeup view of left side of airplane damage. (Courtesy of FAA)



Photograph 3 - View of tire skid marks into the grass of the left side of the runway. (Courtesy of FAA)



Photograph 4 - View of damaged runway light. (Courtesy of FAA)