

ERA25LA232

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the fuselage/hull. (Courtesy of FAA)



Photograph 2 - View of damage to the left side of the fuselage/hull. (Courtesy of FAA)



Photograph 3 - View of damage to the internal fuselage/hull structure. (Courtesy of FAA)