


ERA25LA241

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Side View of Airplane (Courtesy of FAA)



Photograph 2 - Exterior Damage to Lower Right Wing (Courtesy of FAA)



Photograph 3 - Damaged Lower Right Wing Spar (Courtesy of FAA)