

ERA25LA256


INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at the accident site. (Courtesy of Airport Manager)



Photograph 2 - View of damage to the airplane. (Courtesy of Airport Manager)



Photograph 3 - View of the seat cushion strap around control stick. (Courtesy of VCSO)