

ERA25LA257

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of Airport Ops)



Photograph 2 - Right wing strut accident damage (Courtesy of Pilot)



Photograph 3 - Left wing strut accident damage (Courtesy of Pilot)



Photograph 4 - Right side fuselage buckling (Courtesy of Pilot)



Photograph 5 - Left main landing gear damage (Courtesy of Pilot)