

ERA25LA263

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Frontal View of the Airplane On the Runway (Courtesy of FAA)



Photograph 2 -Right Forward Quartering View of the Airplane on the Runway (Courtesy of FAA)



Photograph 3 -Left Rear Quartering View of the Airplane on the Runway (Courtesy of FAA)



Photograph 4 - Left Side View of the Airplane Being Raised from the Runway (Courtesy of FAA)



Photograph 5 - View of the Fuselage Bottom Noting Damage to External Longerons (Courtesy of FAA)



Photograph 6 - Close-Up View Showing Damage to External Longeron (Courtesy of FAA)