

ERA25LA268


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left Wing Damage (Courtesy of FAA)



Photograph 2 - Left Wing Damage (Courtesy of FAA)



Photograph 3 - Broken Engine Mount Beside Nose Gear Retract Cylinder (Courtesy of Mechanic)