

ERA25LA295

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Picture of Accident Aircraft (Courtesy of FAA)



Photograph 2 - Damage to Left Wing, Fuselage, and Landing Gear (Courtesy of FAA)



Photograph 3 - Left Wing Damage (Courtesy of FAA)