

ERA25LA298

INVESTIGATION PHOTOGRAPHS



Photograph 1 -Main wreckage (Courtesy of FAA)




Photograph 2 - Airplane being lifted on runway, NOTE: landing gear down and locked (Courtesy of FAA)



Photograph 3 - Damage to underside of airplane (Courtesy of FAA)



Photograph 4 - Damage to underside of airplane (Courtesy of FAA)



Photograph 5 - Damage to underside of airplane (Courtesy of FAA)