

ERA25LA299

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side fuselage view (Courtesy of FAA)



Photograph 2 - Left upper wing root view (Courtesy of FAA)



Photograph 3 - left wing tip damage (Courtesy of FAA)



Photograph 4 - Lower Firewall (Courtesy of FAA)