

ERA25LA306

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Propeller And Nosewheel Tire Damage (Courtesy of FAA)



Photograph 2 - Firewall Damage (Courtesy of FAA)




Photograph 3 - Cockpit Floor Buckling Damage (Courtesy of FAA)



Photograph 4 - Lower Fuselage Impact Damage (Courtesy of FAA)



Photograph 5 - Bending of Elevator Control Pivot Point (Courtesy of FAA)



Photograph 6 - Closeup View of Bending of Elevator Control Pivot Point (Courtesy of FAA)