

ERA25LA312

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Deformation noted to rudder and vertical stabilizer (Courtesy of FAA)



Photograph 2 - Deformation noted to fuselage skin and right-wing lift strut (Courtesy of FAA)