


ERA25LA319

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of FAA)



Photograph 2 - Left Wing Spar Damage (Courtesy of FAA)