

ERA25LA324

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane at the accident site. (Courtesy of FAA)



Photograph 2 - View of damage to the left wing. (Courtesy of FAA)



Photograph 3 - View of engine mount damage. (Courtesy of FAA)



Photograph 4 - View of fuel sample taken 2 days prior to the accident. (Courtesy of FAA)