

ERA25LA328

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane On-Scene (Courtesy of FAA)



Photograph 2 - Skid Marks from the Braking Application (Courtesy of FAA)



Photograph 3 - Wing Spar Crack (Courtesy of FAA)