


ERA25LA331

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Annotated Google Earth Image Depicting Accident Site Location (Courtesy of Operator of N6185U)**



**Photograph 2 - View of Resting Position of Both Airplanes (Courtesy of FAA)**



**Photograph 3 - View of Resting Position of Both Airplanes (Courtesy of FAA). Note the Damage to the Right Wing of N6185U**



**Photograph 4 - Close up View Showing Right Wing Spar Damage to N6185U (Courtesy of FAA)**



**Photograph 5 - View of Damage to One Propeller Blade of N22998 (Courtesy of FAA)**