

ERA25LA334

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left side of airplane with nose wheel collapse at accident site (Courtesy of FAA)



Photograph 2 - Damaged engine mount and collapsed nose wheel strut (Courtesy of FAA)