

ERA25LA337

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of damage right wing.
(Courtesy of FAA)**



**Photograph 2 - View of broken actuator bolt.
(Courtesy of FAA)**