

ERA25LA355

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Ground structure impacted by airplane (Courtesy of FAA)



Photograph 2 - Skin separations and spar fractures noted to left wing (Courtesy of FAA)