

ERA25LA358

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage, inverted (Courtesy of fire department)



Photograph 2 - View of cockpit (Courtesy of Fire department)



Photograph 3 - damaged tail section (Courtesy of Fire Department)