

ERA25LA376

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident Site (Courtesy of FAA)



Photograph 2 - Left Fuel Cell Breach (Courtesy of FAA)



Photograph 3 - Left Fuel Cell Breach (Courtesy of FAA)