

ERA25LA379

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N533SE Accident Prior to Recovery (Courtesy of Johnstown Airport)



Photograph 2 - Left Forward Landing Gear Bracket Torn from Frame (Courtesy of FAA)



Photograph 3 - Left Forward Landing Gear Strut Punched Through Cockpit Floor (Courtesy of FAA)



Photograph 4 - Right Landing Gear Collapse, Brackets Still Attached (Courtesy of FAA)



Photograph 5 - N533SE Interior Showing ADS-B and Airspeed Markings (Courtesy of FAA)