

ERA25LA380

INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of damaged tail rotor.
(Courtesy of FAA)**