

ERA26LA013

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right-hand side of aircraft nose showing impact damage (Courtesy of Maintenance Facility)



**Photograph 2 - View of underside of fuselage behind firewall showing substantial damage
(Courtesy of Maintenance Facility)**



Photograph 3 - View of right-hand wingtip (Courtesy of Maintenance Facility)



Photograph 4 - View of right-hand wing showing leading edge and spar damage (Courtesy of Maintenance Facility)



**Photograph 5 - View of underside of right-hand wing showing buckling from spar damage
(Courtesy of Maintenance Facility)**