

ERA26LA016

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front End Damage on Accident Aircraft (Courtesy of FAA)



Photograph 2 - Firewall Wrinkling (Courtesy of FAA)



Photograph 3 - Damaged Cockpit-Side Firewall Stiffener (Courtesy of FAA)