

ERA26LA026

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Damage to left side of Tail boom (Courtesy of Operator)



Photograph 3 - Damage to Right side of Tail boom (Courtesy of Oprerator)