

ERA26LA028

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of FAA)



Photograph 2 - Left wing upper skin damage and spar buckling (Courtesy of FAA)



Photograph 3 - Left wing leading edge damage (Courtesy of FAA)



Photograph 4 - Left wing lower skin damage (Courtesy of Pilot)



Photograph 5 - Center hull keel damage (Courtesy of Pilot)



Photograph 6 - Left Main Landing gear sheared actuator bolt (Courtesy of Pilot)



**Photograph 7 - Left main landing gear actuator separated from the landing gear assembly.
(Courtesy of Pilot)**