

ERA26LA030

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Photo of the aircraft at the scene (Courtesy of owner)



Photograph 2 - Photo showing substantial damage to the composite structure of the lower nose (Courtesy of owner)



Photograph 3 - Photo of prop blade after accident with missing nickel leading edge (Courtesy of Catto Propellers)



Photograph 4 - Photo of propeller after the accident showing delamination (Courtesy of Catto Propellers)



Photograph 5 - Photo of damage to propeller as reported to manufacturer May, 2025 (Courtesy of Catto Propellers)