

ERA26LA037

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main Wreckage (Courtesy of Airport Manager)



Photograph 2 - Damage to Left Aileron (Courtesy of Airport Manager)