

ERA26LA043

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N711FA After Landing with Landing Gear Retracted (Courtesy of Dothan Airport)



Photograph 2 - N711FA Prior to Relocation form Runway (Courtesy of Dothan Airport)



Photograph 3 - Abrasion Damage to Fuselage(Courtesy of Dothan Airport)



Photograph 4 - Failed Left Inboard Gear Door Link Assembly (Courtesy of Airplane Owner)



Photograph 5 - Failed Left Aft Inboard Door Hinge (Courtesy of Airplane Owner)